



NORTHEAST POWER COORDINATING COUNCIL, INC.  
1040 AVE. OF THE AMERICAS, NEW YORK, NY 10018 (212) 840-1070 FAX (212) 302-2782

## Regional Standard Processes Manual Comments

Chris Overberg from Con-Edison comment:

### 8. Process for correcting ERRATA

From time to time, an error including but not limited to printing or writing, such as misspellings, omissions, and other typographical errors. May be discovered in a regional standard after it has received final ballot approval by the NPCC ballot body. **Such errors maybe corrected by the RSC without re-balloting if the RSC approves the correction of the error does not change the scope**, applicability or intent of the associated regional standard, and agrees that the correction has no material impact on the compliance obligations of registered entities.

Consider rewording, for example:

“Such errors may be corrected by the RSC without re-balloting if the RSC approves the correction of the error and the correction does not change the scope...”

Respond to comment:

Thank you for your comments. The review team will change the language accordingly and since it is not a substantive change. We are not required to repost this for another 30-day comment period.



**NORTHEAST POWER COORDINATING COUNCIL, INC.  
1040 AVE. OF THE AMERICAS, NEW YORK, NY 10018 (212) 840-1070 FAX (212) 302-2782**

Leonard Kula from IESO comment:  
The IESO supports the proposed changes.

Respond to comment:  
Thank you for your comments.