



NORTHEAST POWER COORDINATING COUNCIL, INC.
1040 AVE. OF THE AMERICAS, NEW YORK, NY 10018 (212) 840-1070 FAX (212) 302-2782

To: NPCC Registered Entities
From: Stanley E. Kopman, Assistant Vice President – Compliance Registration and
Subject: Clarification - Dynamic Disturbance Recording (DDR) in PRC-002-NPCC-01
Date: February 28, 2014

This clarification is being issued to document the NPCC position on Requirement 8 (R8) and Requirement 9 (R9) of PRC-002-NPCC-01:

- All DDRs installed after October 20, 2011:
 - Must function as continuous recorders
 - Must only meet sub-requirement R9.2
 - Do not have to meet sub-requirements R9.1 and R9.3
- Continuous DDRs installed prior to October 20, 2011 must only meet sub-requirement R9.2.
- Non-continuous DDRs installed prior to October 20, 2011:
 - Must meet all three sub-requirements: R9.1, R9.2, and R9.3
 - Do not have to be upgraded to function as continuous recorders

This clarification related to PRC-002-NPCC-01 can be found on the NPCC website under: “Standards”, “NPCC BOD Approved Standards”.

Sincerely,

Stanley E. Kopman

Stanley E. Kopman
Assistant Vice President, Compliance Registration and Enforcement
NPCC, Inc.